

2216Z 19 JAN 1963

TOP SECRET

25X1

DIRECTOR

25 YEAR RE-REVIEW

OPS (1-2-3-4-5)

EMERGENCY

S/C (6)

IN 63057

TOR: 2256Z 19 JAN 1963

25X1

EMERG

0601

REF A 0533

B 0535

C 1985

REF A PARA D. AT 0523Z PILOT OBSERVED BOTH [REDACTED] WARNING LIGHTS COME ON FOR APPROX 20 SEC, AND THEN GO OUT. THIS OCCURRED TOTAL OF THREE TIMES OVER APPROX 2 MIN PD. WHILE LIGHTS WERE ON PILOT HAD STTOBE ON SCOPE INDICATING POSSIBLE FRUIT SET SITE DIRECTLY AHEAD. ALSO HAD HIGH PITCHED AUDIO SIMILAR TO FRUIT SET. AT THIS TIME HE MADE LEFT 90 DEG TURN AND LOST INDIC. DURING PERIOD 0630-0700Z PILOT HAD INTERMITTENT AND VERY WEAK [REDACTED] INDICATIONS SUCH THAT BARELY READABLE AND UNABLE DETERMINE BEARING. POSSIBLY SAME SITE.

END OF MESSAGE

TOP SECRET

REPRODUCTION BY OTHER THAN ISSUING OFFICE IS PROHIBITED.

Copy No.